


Index No. A 21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 2 Corner common to sections 1, 2 AND 35, 36 - 144-26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>CEDAR</u>	<u>CEDAR</u>	<u>CEDAR</u>	<u>BIRCH</u>
Diameter	<u>7"</u>	<u>15"</u>	<u>10"</u>	<u>14"</u>
Bearing	<u>S9W</u>	<u>S41E</u>	<u>N27E</u>	<u>N57W</u>
Distance	<u>20 LKS</u>	<u>50 LKS</u>	<u>40 LKS</u>	<u>35 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By WM. OSUPSEN
Location filed _____
Monument 2" x 54" BR CAP
8' STUBB SIGN POST 3.9 EAST, 4.5 WEST

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>
Diameter	<u>4"</u>	<u>3"</u>	<u>4"</u>	<u>4"</u>
Bearing	<u>N84W</u>	<u>N56E</u>	<u>S49E</u>	<u>S56W</u>
Distance	<u>48.30</u>	<u>25.25</u>	<u>25.12</u>	<u>21.07</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERT BY WM. OSUPSEN 1990
DOC # 323146

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____