


Index No. A 23

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
N1/4 1 Corner common to sections LAND 36-144-26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. PINE</u>	<u>W. PINE</u>	_____
Diameter	<u>10"</u>	<u>12"</u>	_____
Bearing	<u>S51E</u>	<u>N33E</u>	_____
Distance	<u>10 LKS</u>	<u>8 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By W. OSUPSEN
Location filed _____
Monument 2" x 48" BR/CAP

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

STEEL SIGN POSTS EAST 4.0, SOUTH 4.0

Bearing Trees, Reference Objects

Species	<u>MAPLE</u>	<u>MAPLE</u>	<u>BALSAM</u>
Diameter	<u>7"</u>	<u>8"</u>	<u>14"</u>
Bearing	<u>N15E</u>	<u>S23W</u>	<u>S75W</u>
Distance	<u>32.64</u>	<u>37.30</u>	<u>15.94</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By WM OSUPSEN
Location filed _____
Monument CERT. FILE 1990 WM OSUPSEN
DOC # 323147

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____