


Index No. A 6-7

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____

MC Corner common to sections 5 and 32-144-26

Right Bank Leech Lake River



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1922
Original monument 4x4"x6 1/2" long Cedar post 4' in ground

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species No B.T.S Available
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____