Index No. A 7-8

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____

MC Corner common to sections 5 and 32-144-26

Left Bank of Leech Lake River



EXISTING SURVEYS

Original Government Survey

Year surveyed 1922

Original monument 4x4" x 6½' long Cedar post 4½' in ground

Bearing Trees

Species No Bits Available

Diameter

Bearing

Distance

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species

Diameter

Bearing

Distance

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species

Diameter

Bearing

Distance

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____