


Index No. A7-8

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____

MC Corner common to sections 5, 32-144-26

RIGHT BANK Leech Lake River



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1922

Year of search _____ By _____

Original monument 4x4"x6 1/2" Long Cedar post 4 1/2' in ground

Monument found _____

Bearing Trees

Original Bearing Trees Found

Species NO B.T.S Available

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____

Year of search _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed _____

Monument _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____