


Index No. A 7-8

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

MC Corner common to sections 5, 32

Left Bank of Leech Lake River



○ = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1922

Year of search \_\_\_\_\_ By \_\_\_\_\_

Original monument 4x4' x 6 1/2' long Cedar post 4 1/2" in ground

Monument found \_\_\_\_\_

Bearing Trees

Original Bearing Trees Found

Species NO B.T.S AVAILABLE

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_