


Index No. C 17

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
E1143 Corner common to sections 2,3



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>CEDAR</u>	<u>SPRUCE</u>
Diameter <u>5"</u>	<u>4"</u>
Bearing <u>S55E</u>	<u>N72W</u>
Distance <u>6 LKS</u>	<u>20 LKS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1919 By JAMES FLYNN
Location filed COUNTY BOOK "C" P180
Monument FIND OLD CANT B.T.S? STUMP 8" CEDAR
S55E 6 LKS, STUMP 6" SPRUCE N72W 28 LKS
SET POST

Evidence of Subsequent Corner Restoration

Year of search 1922 By GLO
Set 2x36" lip. w/ brass cap
1/4
53/52
1922

Bearing Trees, Reference Objects

Species <u>BALM GILEAD</u>	<u>CEDAR STUMP</u>
Diameter <u>20"</u>	<u>20"</u>
Bearing <u>N78-30E</u>	<u>S11W</u>
Distance <u>36.5'</u>	<u>22.5'</u>

Bearing Trees, Reference Objects

<u>Ash</u>	<u>Poplar</u>
<u>6"</u>	<u>18"</u>
<u>N49E</u>	<u>S60-30W</u>
<u>17 LKS</u>	<u>19 LKS</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1971, FILED IN 1971
Doc. # 246199

1990 CERT. BY Wm. OSUFSEN		
<u>ASH</u>	<u>ASH</u>	<u>ASH</u>
<u>4"</u>	<u>10"</u>	<u>6"</u>
<u>N43W</u>	<u>N48E</u>	<u>S41W</u>
<u>9.61</u>	<u>10.89</u>	<u>24.89</u>

1990 Certificate William Osufsen
Doc. # 319607

STEEL SIGN POST 2.4 SOUTH

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____