


Index No. C 21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 2 Corner common to sections 42



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>TAM.</u>	<u>TAM.</u>	_____
Diameter	<u>8"</u>	<u>6"</u>	_____
Bearing	<u>N60E</u>	<u>S75W</u>	_____
Distance	<u>4LKS</u>	<u>6LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By Wm. OSURSEN  
Location filed \_\_\_\_\_  
Monument 2" x 40" BR/CAP

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>CEDAR</u>	<u>CEDAR</u>	<u>CEDAR</u>	_____
Diameter	<u>5"</u>	<u>6"</u>	<u>5"</u>	_____
Bearing	<u>N58E</u>	<u>S72E</u>	<u>S53W</u>	_____
Distance	<u>20.31</u>	<u>6.20</u>	<u>8.37</u>	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search 1990 By CERT. WM. OSURSEN  
Doc # 323148