


Index No. E 21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 11 Corner common to sections 1, 2, 11, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>SPRUCE</u>	<u>SPRUCE</u>	<u>TAM</u>	<u>CEDAR</u>
Diameter <u>10"</u>	<u>7"</u>	<u>5"</u>	<u>8"</u>
Bearing <u>S45W</u>	<u>N12W</u>	<u>N36E</u>	<u>S21E</u>
Distance <u>6LKS</u>	<u>4LKS</u>	<u>3LKS</u>	<u>25LKS</u>

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1990 By WM. OSUFSEN
Location filed _____
Monument SET 2" x 48" BR/CAP

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

4' STEEL SIGNPOSTS NORTH 2.9, WEST 2.9

Bearing Trees, Reference Objects

Species	Bearing	Trees	Reference Objects
<u>ELM</u>	<u>CEDAR</u>	<u>ASH</u>	<u>ASH</u>
Diameter <u>6"</u>	<u>10"</u>	<u>6"</u>	<u>4"</u>
Bearing <u>N22W</u>	<u>N60E</u>	<u>S24E</u>	<u>S83W</u>
Distance <u>25.13</u>	<u>25.90</u>	<u>21.15</u>	<u>13.23</u>

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration E 21

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERT BY WM. OSUFSEN 1990
Doc # 323150

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____