


T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
N 14 12 Corner common to sections 412



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees	
Species	<u>SPRUCE</u>	<u>W. PINE</u>
Diameter	<u>12"</u>	<u>10"</u>
Bearing	<u>N 52 W</u>	<u>S 48 E</u>
Distance	<u>15 LKS</u>	<u>50 LKS</u>

Original Bearing Trees Found		
Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By WM. OSUFSEN
Location filed _____
Monument SET 2" X 4" BR/CAP

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

8' STEEL SIGN POST NORTH 3.3', EAST 1.5'

	Bearing Trees, Reference Objects		
Species	<u>SPRUCE</u>	<u>SPRUCE</u>	<u>MAPLE</u>
Diameter	<u>6"</u>	<u>5"</u>	<u>7"</u>
Bearing	<u>N 23 W</u>	<u>N 2 E</u>	<u>S 37 W</u>
Distance	<u>33.49</u>	<u>19.19</u>	<u>56.98</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration E-23

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERT by WM. OSUFSEN 1990
Doc. # 323151