


Index No. G-17

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 10 Corner common to sections 10, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument lost  
ENTER SPRUCE & TAM 1 CH. N. SW E E

Bearing Trees  
Species ASPEN SPRUCE  
Diameter 5" 4"  
Bearing S 46 E N 31 W  
Distance 6 LKS 6 LKS

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1916 By E. B. HORST  
Location filed COUNTY BOOK "P" 171  
Monument IND GOVT B.T. 6" SPRUCE N 31 W 6 LKS,  
PARTLY OBLITERATED.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1990 By W. M. OSVENSEN  
SET 2" X 54" BR/CAP  
8' STEEL SIGN POSTS EAST 4.2, SOUTH 4.1

Bearing Trees, Reference Objects

<u>CEDAR</u>	<u>CEDAR</u>	<u>CEDAR</u>
<u>5 72 E</u>	<u>7"</u>	<u>6"</u>
<u>37.30</u>	<u>S 40 E</u>	<u>SOUTH</u>
	<u>37.10</u>	<u>38.56</u>

Subsequent Corner Restoration G-17

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERT. BY W. M. OSVENSEN 1990  
Doc # 323153

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_