


Index No. 621

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 11 Corner common to sections 11, 12



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1872  
Original monument POST

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species W. PINE FIR  
Diameter 12" 4"  
Bearing N32W S45E  
Distance 15 LKS 20 LKS

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1916 By E. B. HORST  
Location filed COUNTY BOOK 2 P. 172  
Monument SET PROPORTIONALLY

Evidence of Subsequent Corner Restoration  
Year of search 1990 By WM. OSUFSEN  
END 2"x6" BR/CP  
STEEL FENCE POST N. 3.6

Bearing Trees, Reference Objects  
Species W. PINE STUMP N. PINE STUMP  
Diameter 24" 16"  
Bearing S42E N19 1/2 W  
Distance 65.4' 66.8'

Bearing Trees, Reference Objects  
BALSAM ELM BALSAM  
6" 7" 6"  
N65W S14E S78W  
145.95 3652 116.15

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1969  
CERT. OSUFSEN 1990  
DOC. # 319610

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_