


Index No. J17

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 15 Corner common to sections 10, 11, 14, 15



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	<u>SPRUCE</u>	<u>ASPEN</u>	<u>SPRUCE</u>	<u>SPRUCE</u>
Diameter	<u>10"</u>	<u>7"</u>	<u>6"</u>	<u>4"</u>
Bearing	<u>N 39E</u>	<u>N 36W</u>	<u>S 75W</u>	<u>S 24E</u>
Distance	<u>20 LKS</u>	<u>15 LKS</u>	<u>5 LKS</u>	<u>10 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By WM. OSUFSEN
Location filed _____
Monument 2" x 54" BR/CAP

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

8' STEEL SIGN POSTS NORTH 4.6', SOUTH 4.1'

Species	Bearing Trees, Reference Objects			
	<u>MAPLE</u>	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASH</u>
Diameter	<u>5"</u>	<u>6"</u>	<u>10"</u>	<u>4"</u>
Bearing	<u>N 27E</u>	<u>N 7SE</u>	<u>S 89E</u>	<u>S 14E</u>
Distance	<u>50.52</u>	<u>34.66</u>	<u>30.63</u>	<u>72.86</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration I-17

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERT. BY WM. OSUFSEN 1990
Doc. # 323154

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____