


Index No. J 21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 54 Coordinates: X _____ Y _____
NE 14 Corner common to sections 11, 12, 13, 14



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>W.PINE</u>	<u>N.PINE</u>	<u>W.PINE</u>	<u>N.PINE</u>
Diameter	<u>5"</u>	<u>8"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>S25W</u>	<u>N65W</u>	<u>N26E</u>	<u>S35E</u>
Distance	<u>10LKS</u>	<u>25LKS</u>	<u>12LKS</u>	<u>30LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By WM OSUPSEN
Location filed _____
Monument 2 1/2" CAPPED GALV. PIPE

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

8' STEEL SIGN POSTS NORTH 3.5, EAST 3.5

	Bearing Trees, Reference Objects			
Species	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>
Diameter	<u>10"</u>	<u>10</u>	<u>10"</u>	<u>10"</u>
Bearing	<u>N77W</u>	<u>N48E</u>	<u>S57E</u>	<u>S41W</u>
Distance	<u>44.71</u>	<u>19.05</u>	<u>10.22</u>	<u>72.03</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERT. BY WM. OSUPSEN 1990
DOC. # 323156

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____