


Index No. J 23

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
N 14 13 Corner common to sections 12, 13



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>TAM</u>	<u>S 70 E</u>	<u>SPRUCE</u>
<u>8"</u>	<u>4"</u>	
<u>N 51 W</u>	<u>S 32 W</u>	
<u>10 LKS</u>	<u>18 LKS</u>	

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By WM OSUPSEN
Location filed _____
Monument 2" x 54" BR. CAP

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

8" STEEL SIGN POSTS NORTH 4.3, EAST 4.1

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>CEDAR</u>	<u>N 80 W</u>	<u>32.25</u>
<u>CEDAR</u>	<u>N 23 E</u>	<u>25.59</u>
<u>ASH</u>	<u>S 70 E</u>	<u>36.74</u>
<u>12"</u>	<u>7"</u>	<u>6"</u>

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERT. BY WM OSUPSEN 1990
Doc. # 323157

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____