


Index No. J7

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 17 Corner common to sections 8, 17



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Cedar</u>	<u>Cedar</u>	_____
Diameter	<u>10"</u>	<u>4"</u>	_____
Bearing	<u>S54E</u>	<u>N47E</u>	_____
Distance	<u>6 LKS</u>	<u>15 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By GLO
Location filed Sec. of State
Monument Set 2x36" I.P. w/ brass cap 1/4" 58
517
1922

Evidence of Subsequent Corner Restoration

Year of search 1968 By William Okerman
found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Tam</u>	_____
Diameter	<u>14"</u>	<u>24"</u>	_____
Bearing	<u>N43E</u>	<u>S69-15E</u>	_____
Distance	<u>221 LKS</u>	<u>236 LKS</u>	_____

Bearing Trees, Reference Objects

Cedar	Cedar	Cedar
6"	8"	6"
N10W	N50W	S71W
67.35'	58.55'	21.43'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - B. H. Okerman - 1968 filed 1971

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____