


Index No. L 21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 574 Coordinates: X _____ Y _____
E 74 14 Corner common to sections 13, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Bearing Trees

Species	<u>TAM</u>	<u>SPRUCE</u>	
Diameter	<u>10"</u>	<u>8"</u>	
Bearing	<u>S51W</u>	<u>S53E</u>	
Distance	<u>120KS</u>	<u>40KS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1990 By W.M. OSUPSEN
Location filed _____
Monument 2" x 54" BR/CAP IN PLACE OF 2" I.P.
8' STEEL SIGN POSTS NORTH 3.6', WEST 3.0'

Bearing Trees, Reference Objects

Species	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>
Diameter	<u>12"</u>	<u>7"</u>	<u>14"</u>
Bearing	<u>N46W</u>	<u>N15W</u>	<u>N46E</u>
Distance	<u>22.07</u>	<u>35.78</u>	<u>21.05</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration L-21

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERT. by W.M. OSUPSEN 1990
Doc # 323159

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____