


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ by _____

Monument found _____

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed: _____

Monument: _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Location filed: _____

Monument: _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed: _____

Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Location filed: _____

Monument: _____

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 21 Corner common to sections 15, 16, 21, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument Post

Species	Bearing	Tree	Distance
<u>BIRCH</u>	<u>CE</u>	<u>CE</u>	<u>5LKS</u>
<u>BIRCH</u>	<u>SE</u>	<u>CE</u>	<u>5LKS</u>
<u>BIRCH</u>	<u>SW</u>	<u>CE</u>	<u>15LKS</u>
<u>BIRCH</u>	<u>NE</u>	<u>CE</u>	<u>12LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed ? By GEO. RALPH

Location filed COUNTY SURVEY RECORD BOOK B" 198-99

Monument Two Post - OLD B.T. CEDAR S27E 3'

also on microfilm - roll 115 BK82 P44

Evidence of Subsequent Corner Restoration

Year of search 1922 By GLO

Found 4x4" cedar post Set 2x36" 1/2" w/ brass cap

0.50 CH N. OF TREE COR.

<u>T143N</u>	<u>R26W</u>
<u>S16</u>	<u>S15</u>
<u>S21</u>	<u>S22</u>

WC
1922

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance
<u>POPULAR</u>	<u>N20W</u>	<u>POPULAR STUMP</u>	<u>37.4'</u>
<u>POPULAR</u>	<u>S19E</u>	<u>POPULAR</u>	<u>46.7'</u>
<u>POPULAR</u>	<u>S3W</u>	<u>POPULAR</u>	<u>53'</u>
<u>CE</u>	<u>N47-30E</u>	<u>CE</u>	<u>54.5'</u>

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance
<u>POPULAR</u>	<u>S40-15E</u>	<u>POPULAR</u>	<u>168LKS</u>
<u>SPRUCE</u>	<u>S49-15W</u>	<u>SPRUCE</u>	<u>189LKS</u>

Subsequent Corner Restoration

Year surveyed 1959 By DNR-Engineering

Location filed Map & notes in file

Monument Found brass cap monument 33' N. of 6
set spike in Road

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - John Walker - DNR - 1988

DOL # 303,529

set 1 1/4" x 1 1/4" x 20" mon. w/ alum. cap

w. Spruce 15" N48W 81.01'

Spruce 15" N8W 50.80'

Brass cap witness North 33.00'

Steel fence post S35W 78.66'

" " " S17E 88.89'

Power Pole S65E 98.75'

Brass cap 33' N.

Tele. Pole NW 47.24'

8" Aspen SSW 92.90'

1975- DNR - set 16 penny spike

Capped 2" 1/2" l.p. marked w.c. N. 33.00'

iron pipe SSE 101.00'

SE edge tele. junct box NW 104.70'

B.C. Spruce NNW 50.80'

Oct. 2003 M. Stefan # 12261

GLO Monument found

1962? Co. Hwy Dept. - Co. Rd # 65

w.c. l.p. in place - also spike 47.3' South

Ties to spike: 6" Poplar SE 53.1', 10" Poplar SW 75.3'

8" Poplar SSW 58.3'

1925- Co. Hwy Dept. - State Rd # 4, corner

ties: tele. pole SE 31.5'

USGLO w.c. N 33.0'