

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. N 23

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
N 14 24 Corner common to sections 13, 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species BIRCH PINE
Diameter 4" 4"
Bearing N49E S18W
Distance 5 LKS 12 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 7 By GEO RALPH
Location filed COUNTY SURVEY RECORD BOOK B' P. 98-99
Monument FIND OLD POST - OLD B.T.: 4" ANE S18-30W
11.8', 14" BIRCH N42E 3.5'
also on microf. film - roll 115 BK82 P. 46

Evidence of Subsequent Corner Restoration

Year of search 1990 By Wm. OSVENSEN
SET 2x24" BR/CAP 3' N OF E CORN. 65
SET 8" STEEL SIGN POST 35' ± NORTH

Bearing Trees, Reference Objects

Species POPLAR PINE STUMP
Diameter 3"
Bearing S33-30E N8E
Distance 58.0' 59.3'

Bearing Trees, Reference Objects

W. OAK W. OAK ASPEN
8" 10" 11"
N44W N11E S10W
143.69 104.64 63.00

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERT. BY Wm. OSVENSEN 1990
DOC. # 325143

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____