

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects


Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:



T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 24 Corner common to sections 13, 24 AND 18, 19-143-25

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1872
 Original monument POST

Species	Bearing	Tree	Distance
<u>MAPLE</u>	<u>542E</u>	<u>11LKS</u>	
<u>MAPLE</u>	<u>N 27 W</u>	<u>13LKS</u>	
<u>SPRUE</u>	<u>525W</u>	<u>21LKS</u>	
<u>BIRCH</u>	<u>N 53 1/2 E</u>	<u>30LKS</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 7 By Geo. Ralph
 Location filed County Survey Record Book 13 P. 98-99
 Monument Iron Old Post - Old B.T. : 12" BIRCH N49E 18'
also on microfilm - roll 115 BK 82 P. 48

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>MAPLE</u>	<u>541E</u>	<u>44.3'</u>
<u>BIRCH</u>	<u>N1E</u>	<u>58.1'</u>
<u>STUB</u>	<u>S13W</u>	<u>51.2'</u>

Evidence of Subsequent Corner Restoration
 Year of search 1976 By BLM
SET 5" COPPERWELD 6" BELOW SURFACE W/ COPPER CAP
T143N
R26W R25W
513 | 518
524 | 519

Bearing Trees, Reference Objects BLM 1976

Species	Bearing	Distance
<u>ALUM POST W/CAP</u>	<u>2 1/2 x 28"</u>	<u>N71E 129.0'</u>
<u>ALUM POST W/CAP</u>	<u>2 1/2 x 28"</u>	<u>N69W 132.2'</u>

Subsequent Corner Restoration
 Year surveyed 1990 By Wm OSUFSEN
 Location filed _____
 Monument 5" COPPERWELD ROD BY BLM

Bearing	Tree	Distance
<u>4"</u>	<u>8"</u>	<u>10"</u>
<u>N40E</u>	<u>S17E</u>	<u>S32W</u>
<u>119.4'</u>	<u>68.79</u>	<u>76.07</u>

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERT. - Wm. OSUFSEN 1990
DOC. # 319617