


Index No. N3

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 19 Corner common to sections 18, 19



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	<u>Birch</u>	<u>Birch</u>	Trees	_____
Diameter	<u>6"</u>	<u>4"</u>	_____	_____
Bearing	<u>N61W</u>	<u>S35W</u>	_____	_____
Distance	<u>15 LKS</u>	<u>21 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed ? By Geo. Ralph
Location filed County Survey Record Book B P 98
Monument Iron nail post - old B.T. 8' Birch N35-30W
11'
also on microfilm - roll 115 BK 82 P. 42

Evidence of Subsequent Corner Restoration

Year of search 1925 By Co Hwy Dept.
State Rd # 9
Corner

Bearing Trees, Reference Objects

Species	<u>BIRCH</u>	<u>SPRUCE</u>	_____	_____
Diameter	<u>8"</u>	<u>6"</u>	_____	_____
Bearing	<u>N 3-30W</u>	<u>S 23E</u>	_____	_____
Distance	<u>46'</u>	<u>43.2'</u>	_____	_____

Bearing Trees, Reference Objects

<u>Tele. pole</u>	<u>Spruce Stake</u>	_____	_____
	<u>6"</u>	_____	_____
<u>SW</u>	<u>SE</u>	_____	_____
<u>43.0'</u>	<u>43.2'</u>	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1986 Certificate - Ken Whitehorn
Doc # 289670
Set 2 1/2" x 24" galvanized iron pipe with
3" stamped brass tablet
4" Aspen N18W 83.57'
6 1/2" Ash S4W 128.83'
7" Birch S42E 149.39'

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____