


Index No. R 13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 28 Corner common to sections 21, 22, 27, 28



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1872
Original monument POST

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>SPRUCE</u>	<u>CEDAR</u>	<u>SPRUCE</u>	<u>BIRCH</u>
Diameter	<u>18"</u>	<u>6"</u>	<u>10"</u>	<u>16"</u>
Bearing	<u>N6E</u>	<u>S65E</u>	<u>S60W</u>	<u>N55W</u>
Distance	<u>30LKS</u>	<u>3BLKS</u>	<u>60LKS</u>	<u>20LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1990 By WM. OSVENSEN
Location filed _____
Monument 2" x 54" BR/CAP

Year of search _____ By _____

8' STEEL SIGN POSTS NORTH 3.3', EAST 3.3'

	Bearing Trees, Reference Objects			
Species	<u>MAPLE</u>	<u>BALSAM</u>	<u>MAPLE</u>	<u>ASH</u>
Diameter	<u>6"</u>	<u>10"</u>	<u>6"</u>	<u>1.5"</u>
Bearing	<u>N77W</u>	<u>N40E</u>	<u>S20E</u>	
Distance	<u>26.27</u>	<u>30.99</u>	<u>43.22</u>	<u>23.59</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration R-13

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

CERT. BY N.M. OSVENSEN 1990
Doc. # 323163

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____