


Index No. T13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
E 14 28 Corner common to sections 27, 28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>SPRUCE</u>	<u>CEDAR</u>	_____	_____
Diameter	<u>5"</u>	<u>10"</u>	_____	_____
Bearing	<u>S55W</u>	<u>S4E</u>	_____	_____
Distance	<u>8 YDS</u>	<u>30 YDS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By WM. OSJFSEN
Location filed _____
Monument 2x54 BR/CAP OVER 8" STEEL
SIGN POST.
SET 8" STEEL SIGN POST EAST 3.3, SOUTH 3.4

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>DAK</u>	<u>DAK</u>	<u>ASH</u>
Diameter	<u>8</u>	<u>6</u>	<u>8</u>
Bearing	<u>N60W</u>	<u>N23W</u>	<u>WEST</u>
Distance	<u>90.80</u>	<u>104.80</u>	<u>76.20</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration T-13

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERT BY OSJFSEN 1990
DOC # 355144

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____