


Index No. T 17

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 R 7 Corner common to sections 26, 27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>BIRCH</u>	<u>BIRCH</u>
Diameter <u>12"</u>	<u>8"</u>
Bearing <u>S 47 W</u>	<u>S 79 E</u>
Distance <u>10 LKS</u>	<u>22 LKS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1990 By Wm. OSVESEN  
Location filed \_\_\_\_\_  
Monument SET 2x3Y" BR/CAP

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

SET 8' STEEL SIGN POST 3.9 EAST, 4.7 SOUTH

Bearing Trees, Reference Objects		
Species <u>R. OAK</u>	<u>R. OAK</u>	<u>R. OAK</u>
Diameter <u>8</u>	<u>5</u>	<u>12</u>
Bearing <u>N 43 W</u>	<u>S 84 E</u>	<u>S 66 W</u>
Distance <u>27.35</u>	<u>14.11</u>	<u>24.94</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration T 17

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERT. By Wm OSVESEN 1990  
Dy. # 325145

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_