	r common to sections	Y	-
Octob	EXIS	STING SURVEYS Original Evidence Found	
Origii	nal Government Survey	Original Evidence Found	
Year surveyed		Year of search by	
Original monument		Monument found = Co	
	Bearing Trees	Original Bearing Trees Found	ли
Species	•	Occasion	
Diameter		Diameter	
Dooring		Decring	
Distance		Distance	
Subse	quent Corner Restoration	Evidence of Subsequent Corner Restoration	
Year surveyed	Ву	Year of search By	
Location filed:		Location filed:	
Monument:		Monument:	
	D : T D (OI : .		
0	Bearing Trees, Reference Objects	Bearing Trees, Reference Objects	
		Species	
Danisa		Diameter	
Bearing Distance		Bearing Distance	
Distance			
Subse	quent Corner Restoration	Evidence of Subsequent Corner Restoration Found	_
Year surveyed	Ву	Year of search By	
Location filed:		Location filed:	
Monument:		Monument:	

Index No. 79 CASS COUNTY LAN	D CORNER RECORD
T. 143 R. R. M. STH Coordinates: X E114 29 Corner common to sections 28/29	Y
E79 A7 Corner common to Sections AB/A7	
FXISTIN	G SURVEYS RIP
Original Government Survey	Original Evidence Found
Year surveyed 1872	Year of search By
Original monument Post	Monument found
onginal monument	
Bearing Tress	Original Bearing Trees Found O = Corner
Species Birch Pirch	Species
Diameter 8" 8"	Diameter
Begring N32E S/3W	_ Bearing
Distance 6 LKS 30 LKS	_ Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed 1918 Brok C PISI	Year of search 198/e By Ken Whitehorn
Location filed COUNTY Deal C P137	Set 2/12" x 24 galvanized iron pipe with
Monument SET IRON MON UMENT PROPORTION ALLY	magnet at base and 3" stamped brass
2/2x30" ITON WICAP (OUNTY RESURVEY 1918 "E-3"	tablet.
COUNTY RESURVEY 1718 6-3	
	Descine Trees Beforence Objects
Bearing Trees, Reference Objects Species Frontwood ELM	Bearing Trees, Reference Objects W. Oak W. Oak
120	141/2" 41/2"
Paging N/37E Sig3in	N45W 579W
Distance 47.3' 38.5'	134.74' 69.73'
DISTORCE TUD	
Subsequent Corner Restoration Year surveyed By	Evidence of Subsequent Corner Restoration Found Year of search
Year surveyed By Location filed	Evidence of Subsequent Corner Restoration Found Year of search By 1986 Certificate Ken Whitehorn Tro # 289679
Year surveyed By Location filed	Year of search By
Year surveyed By Location filed	Year of search By
Year surveyed By Location filed	Year of search By
Year surveyed By Location filed	Year of search By
Year surveyed By Location filed Monument	Year of search By
Year surveyed By Location filed	Year of search By
Year surveyed By Location filed	Year of search By
Year surveyed By Location filed	Year of search By
Year surveyed By Location filed	Year of search By
Year surveyed By Location filed	Year of search By
Year surveyed By Location filed	Year of search By