


Index No. V 19

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
N114 35 Corner common to sections 26, 35



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees	
Species	<u>BIRCH</u>	<u>BIRCH</u>
Diameter	<u>8"</u>	<u>7"</u>
Bearing	<u>N10E</u>	<u>S52W</u>
Distance	<u>10 LKS</u>	<u>8 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By WM. OSUFSEN
Location filed _____
Monument 2x54" BR/CAP

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

SET STEEL SIGN POSTS 4.0 EAST, 3.4 SOUTH

Bearing Trees, Reference Objects

	<u>MAPLE</u>	<u>ASPEN</u>	<u>MAPLE</u>
Species			
Diameter	<u>5</u>	<u>10</u>	<u>7</u>
Bearing	<u>N51W</u>	<u>S28E</u>	<u>S60W</u>
Distance	<u>50.07</u>	<u>22.40</u>	<u>39.60</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration V-19

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERT. BY WM. OSUFSEN 1990
DOC. # 325131

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____