


T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 35 Corner common to sections 25, 26, 35, 36



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1872
 Original monument POST

Bearing Trees
 Species BIRCH WILLOW W. PINE BIRCH
 Diameter 14" 8" 12" 8"
 Bearing S14W N40E S14E N65W
 Distance 10LKS 10LKS 30LKS 6LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1979 By USFS
 Location filed CERT BY MILO STEFAN
 Monument 2x60' MON FROM ORIG EVID. BY
CULOTT + KRAUSE (1968)

Evidence of Subsequent Corner Restoration
 Year of search 1990 By WM OSVESEN
END 2" BR/CAP LEARNING - RESET FROM N/S
SET 8" STEEL SIGN POSTS NORTH 4.0, EAST 4.2.

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

ASPEN	R. OAK	R. OAK	R. OAK
13	11	10	12
N42W	N46E	S51E	S35W
63.65	85.48	23.28	76.50
(1968)	(1968)	(1968)	(1968)

Subsequent Corner Restoration V-21
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1968 - FILED IN 1979
DOC. # 246188
CERT BY WM. OSVESEN 1990
DOC. # 325152