

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 32 Corner common to sections 29, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Bearing	Trees
<u>Birch</u>	<u>Birch</u>	
Diameter <u>10"</u>	<u>6"</u>	
Bearing <u>S42E</u>	<u>N81W</u>	
Distance <u>18LKS</u>	<u>5LKS</u>	

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1916 By JAMES FLYNN
 Location filed County Book "C" P. 161
 Monument Find old cast BT: 10" BIRCH STUBS
S42E 18LKS
1918 JAMES FLYNN Book "C" P. 151 SET IRON
From 1916 TIES IRON IS 2 1/2 x 30" W/ CAP
COUNTY RESERVE 1918 "E-3"
 Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. PINE</u>	<u>DRY W BIRCH</u>	
Diameter <u>12"</u>	<u>10"</u>	
Bearing <u>N41W</u>	<u>S34W</u>	
Distance <u>57.5'</u>	<u>45.5'</u>	

1916 TIES

Evidence of Subsequent Corner Restoration

Year of search 1969 By Co. Hwy Dept
(Co. Rd # 65)
Found corner monument

Bearing Trees, Reference Objects

Subsequent Corner Restoration V-7

Year surveyed 1983 By Ken Whitehorn
 Location filed Certificate - Dec. # 277308
 Monument Certificate shows info from front of card
and info from 1969-1979 Certificate of Milo Stefan
in 1983 Ken Whitehorn find the ties of 1969 Certificate
 Ties: 12.7" W. oak N 2° E 70.46'
9.8" W. oak N 43° E 92.82'
Rweepde 55° W 52.65'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1969 - FILED IN 1979
Doc. # 246200
Cert. F. code - Ken Whitehorn - USFS - 1984

1916 Co DITCH SURVEY BK 7 Box 2 OF
Co DITCH SURVEY BOOKS - PG 61