


T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
E 1/4 34 Corner common to sections 34, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument POST

Bearing Trees

Species	<u>SPRUCE</u>	<u>BIRCH</u>
Diameter	<u>8"</u>	<u>10"</u>
Bearing	<u>N64E</u>	<u>S55W</u>
Distance	<u>15 LKS</u>	<u>30 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By Wm. OSUFSEN

Location filed _____

Monument 2x54" BR./CAP

SET 8' STEEL SIGN POSTS EAST 4.1, SOUTH 4.5

Bearing Trees, Reference Objects

Species	<u>BIRCH</u>	<u>BIRCH</u>	<u>BIRCH</u>
Diameter	<u>6</u>	<u>10</u>	<u>5</u>
Bearing	<u>N28W</u>	<u>S25E</u>	<u>S61W</u>
Distance	<u>23.43</u>	<u>32.42</u>	<u>12.62</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERT. BY Wm. OSUFSEN 1990
Doc # 325156