


Index No. X 21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
E 1/4 35 Corner common to sections 35, 36



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>ASPEN</u>	<u>N 73 E</u>	<u>W. PINE</u>
<u>10"</u>	<u>N 88 W</u>	
<u>10 LRS</u>	<u>7 LRS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By WM. OSVENSEN
Location filed _____
Monument SET 2 X 54 BR/CPD AS WITNEC
CORNER 90.00 FT SO. OF 1/4 COR POSITION
SET 8 STEEL SIGN POSTS NORTH 2.3, SOUTH 2.3

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>MAPLE</u>	<u>6"</u>	<u>N 54 W</u>	<u>36.58</u>
<u>SPRUCE</u>	<u>8</u>	<u>S 67 W</u>	<u>39.32</u>
<u>MAPLE</u>	<u>9</u>	<u>S 79 W</u>	<u>11.25</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration X-21

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERT. BY OSVENSEN 1990
DOC # 325157

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____