Index No. A 23

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____

N1/4 1 Corner common to sections 1 AND 36 - 143 - 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Tam	Tam		
Diameter	12"	5"		
Bearing	S75E	N40W		
Distance	23 LKS	13 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1937 By GLO

Location filed Sec. of State

Monument Set 1x36" I.P. w/brass cap proportionally

1/4 536

51

1937

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Cedar	Tam		
Diameter	6"	6"		
Bearing	N33½E	S86¾W		
Distance	33 LKS	27 LKS		

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____