


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 1 Corner common to sections 1 AND 6-143-26 AND 31-144-26
AND 36-144-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument Post

Species	Bearing	Distance
Birch	S7E	10LKS
Spruce	N73E	15LKS
Spruce	S70W	6LKS
Spruce	N20W	8LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1937 By GLO

Location filed Sec. of State

Monument Set 2' long 7" dia concrete post w/ brass cap

T144N
R27W | R26W
S36 | S31

Species	Bearing	Distance
Ash	N21/2E	55LKS
Cedar	S82 3/4 E	188LKS
Cedar	S66-10W	242LKS
Cedar	N4W	91LKS

Evidence of Subsequent Corner Restoration

Year of search 1968 By William Okerman

Found GLO monument in good condition

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
Ash	6"	N66W	51.85'
Ash	3"	N1E	36.53'

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE BILL OKERMAN - 1968