


T. 143 R. 27 M. 5TH Coordinates: X 4, 5, 8, 9 Y NE 8
Corner common to sections 4, 5, 8, 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees		
Species	<u>Tam</u>	<u>Spruce</u>	<u>Tam</u>	<u>Tam</u>
Diameter	<u>8"</u>	<u>5"</u>	<u>6"</u>	<u>8"</u>
Bearing	<u>N18W</u>	<u>S55W</u>	<u>S25E</u>	<u>N68E</u>
Distance	<u>2745</u>	<u>2345</u>	<u>3145</u>	<u>2145</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1970 By William Okerman
Location filed _____
Monument Set 24" concrete monument with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Aspen</u>	<u>Aspen</u>	<u>Aspen</u>	<u>Spruce</u>
Diameter	<u>9"</u>	<u>9"</u>	<u>12"</u>	<u>8"</u>
Bearing	<u>N23E</u>	<u>N57E</u>	<u>S64E</u>	<u>S47W</u>
Distance	<u>74.80'</u>	<u>79.20'</u>	<u>110.50'</u>	<u>86.20'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1975 Certificate - William Okerman
Doc # 223554