


Index No. L 25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 13 Corner common to sections 13 AND 18-14 3-26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument lost

Bearing Trees

Species	<u>Cedar</u>	<u>Spice</u>	_____
Diameter	<u>6"</u>	<u>6"</u>	_____
Bearing	<u>S50E</u>	<u>S38W</u>	_____
Distance	<u>745</u>	<u>645</u>	_____

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1986 By Ken Whitehorn  
Location filed \_\_\_\_\_  
Monument Set 5/8" x 60" aluminum rod with 3/4" aluminum tablet.

Bearing Trees, Reference Objects

Species	<u>Ash</u>	<u>Ash</u>	<u>Ash</u>
Diameter	<u>6 1/2"</u>	<u>7 1/2"</u>	<u>6"</u>
Bearing	<u>N80W</u>	<u>S13W</u>	<u>N20E</u>
Distance	<u>38.49'</u>	<u>19.75'</u>	<u>32.62'</u>

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1986 Certificate - Ken Whitehorn  
Doc # 289684

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_