


T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
N 1/4 24 Corner common to sections 13, 24



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

| | | | |
|----------|--------------------|--------------|-------|
| Species | <u>Balm Gilead</u> | <u>Fir</u> | _____ |
| Diameter | <u>7"</u> | <u>5"</u> | _____ |
| Bearing | <u>S35E</u> | <u>N4E</u> | _____ |
| Distance | <u>8 LKS</u> | <u>7 LKS</u> | _____ |

Original Bearing Trees Found

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 7 By Geo. Rulph
Location filed County Survey Record Book B' P 97
Monument Find our Post
1915 JOHN CURD FND COR. SET BY STATE ENGINEER.

Evidence of Subsequent Corner Restoration

Year of search 1925 By Co Hunt Dept
State Rpt # 4 BOOK 154 PAGE 25
APPROX. Corner

Bearing Trees, Reference Objects

| | | | |
|----------|----------------|----------------|-----------------------------|
| Species | <u>PINE</u> | <u>POPULAR</u> | <u>BK B' P. 97 - also</u> |
| Diameter | <u>4"</u> | <u>15"</u> | <u>on microfilm -</u> |
| Bearing | <u>S11-30W</u> | <u>N4W</u> | <u>roll 115 BK 82 P. 40</u> |
| Distance | <u>50'</u> | <u>39.5'</u> | _____ |

Bearing Trees, Reference Objects

| | | |
|--------------------|-------------------|-------|
| <u>12" TAM STP</u> | <u>TELE. POLE</u> | _____ |
| <u>SE 12"</u> | _____ | _____ |
| <u>SE</u> | <u>SOUTH</u> | _____ |
| <u>43.7</u> | <u>29.01</u> | _____ |

Geo. Rulph ties

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 1998 By L. Leuelling RLS 16089
Set .6" x 24" galv. steel pipe w/ stamping
in E Co RD. 135. Cap is 10" below surface
of rd. This position perpetuates the surveys
of several USDA and Cass Co. surveys. Located
E 135 and intersection of fence line running
N/S to the North.

- REF. TIES:

| | | |
|-------------------------|--------------------|----------------|
| <u>Steel sign post</u> | <u>N 3° W</u> | <u>35.31'</u> |
| <u>5" Aspen</u> | <u>S 31° E</u> | <u>94.22'</u> |
| <u>6" Maple triplet</u> | <u>S 1° W</u> | <u>104.96'</u> |
| <u>Mound</u> | <u>S 11° 30' W</u> | <u>50.00'</u> |

CERT. OF LOCATION 5/17/99
DOC. # 412848