


Index No. R11

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
N14 28 Corner common to sections 21, 28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Birch</u>	<u>W. Pine</u>	_____	_____
Diameter	<u>6"</u>	<u>24</u>	_____	_____
Bearing	<u>N19W</u>	<u>S11E</u>	_____	_____
Distance	<u>7LKS</u>	<u>8LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1998 By NLSEM RLS #16089
Set a 2" x 24" galv. steel pipe w/ brass cap, below road surface.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Oak</u>	<u>Aspen</u>	<u>P. Pole</u>	<u>steel</u>
<u>12"</u>	<u>6"</u>		<u>sqn post</u>
<u>N3°E</u>	<u>N60°W</u>	<u>S35°W</u>	<u>N5°W</u>
<u>31.40'</u>	<u>57.91'</u>	<u>46.67</u>	<u>28.64</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at CCRO Dec. # 412853

By NLSEM
Date 5/17/99