


Index No. R 19

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
N 14 36 Corner common to sections 23, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Bearing Trees

Species	<u>Fir</u>	<u>Cedar</u>	_____
Diameter	<u>8"</u>	<u>8"</u>	_____
Bearing	<u>N 12 W</u>	<u>S 39 W</u>	_____
Distance	<u>18 LKS</u>	<u>16 LKS</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1999 By L. LEWELLING (NLSM)
Set a brass capped pipe at a "lost" position, midway and on line, between sec. 23 & 26.
CERT. OF LOCATION 5-30-99
DOC. NO. 413419

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Ash</u>	<u>Balm of Gail.</u>	<u>St. sign post</u>	<u>W. Pine</u>
<u>9"</u>	<u>6"</u>	_____	<u>18"</u>
<u>N 10° W</u>	<u>S 10° E</u>	<u>S 59° W</u>	<u>N 64° W</u>
<u>22.82'</u>	<u>1.84'</u>	<u>4.76'</u>	<u>162.68'</u>
<u>(6.956m)</u>	<u>(0.560m)</u>	<u>(1.450m)</u>	<u>(49.584m)</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____