


Index No. R 21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5th Coordinates: X _____ Y _____

NE 26 Corner common to sections 23, 24, 25, 26



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing Trees			
	Fir	Fir	Fir	Fir
Diameter	<u>6"</u>	<u>6"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>N47E</u>	<u>S65E</u>	<u>N33W</u>	<u>S38W</u>
Distance	<u>9LKS</u>	<u>11LKS</u>	<u>14LKS</u>	<u>15LKS</u>

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search APRIL 1999 By L. LEVELLING #16089
SET BRASS CAPPED IRON PIPE ON EAST SIDE
OF TOWNSHIP ROAD
CERT. OF LOCATION DOC. # 412250

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>0.102m B of GL</u>	<u>0.110 m ASPEN</u>	<u>0.102m OAK</u>	<u>0.142m B of G</u>
<u>N79°W</u>	<u>N59°E</u>	<u>S11°E</u>	<u>S52°W</u>
<u>13.348 m</u>	<u>25.500 m</u>	<u>7.849 m</u>	<u>13.348 m</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____