


T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
N14 25 Corner common to sections 24, 25



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Species	Bearing	Trees
<u>Fir</u>	<u>Maple</u>	
<u>16"</u>	<u>15"</u>	
<u>555W</u>	<u>N 28W</u>	
<u>16 LKS</u>	<u>37 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By John Curo

Location filed COUNTY BOOK 'B' P. 45-462

Monument Four Old Gov't Bits: 15" Maple N18W (not 28)
37 LKS, STUMP 16" FIR S85W (not 55) 16 LKS,
Set 4x4x36" stake
- also on microfilm - roll 115 BK 79 P. 20

Species	Bearing	Trees, Reference Objects
<u>W. Pine</u>	<u>Birch</u>	
<u>12"</u>	<u>14"</u>	
<u>538W</u>	<u>559E</u>	
<u>54.10'</u>	<u>39.30'</u>	

Evidence of Subsequent Corner Restoration

Year of search 1998 By NLSEM PLS #16089

Set a 2" x 48" galv. steel pipe w/ brass cap

Species	Bearing	Trees, Reference Objects
<u>Maple</u>	<u>Maple</u>	<u>Basswood</u>
<u>7"</u>	<u>7"</u>	<u>8"</u>
<u>N54°E</u>	<u>S69°E</u>	<u>N70°W</u>
<u>3.44'</u>	<u>25.72'</u>	<u>22.45'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____