


Index No. R 25

CASS COUNTY LAND CORNER RECORD



T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 25 Corner common to sections 24, 25 AND 19, 30-143-26

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>soft maple</u>	<u>Sugar</u>	<u>Linden</u>	<u>Sugar</u>
Diameter	<u>6"</u>	<u>8"</u>	<u>8"</u>	<u>10"</u>
Bearing	<u>N64E</u>	<u>S29E</u>	<u>S62W</u>	<u>N10W</u>
Distance	<u>10 LKS</u>	<u>21 LKS</u>	<u>14 LKS</u>	<u>20 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1986 By Ken Whitehorn
Location filed _____
Monument Set 2 1/2" x 60" galvanized iron pipe with magnet at base and 3" stamped brass tablet up 18"

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Maple</u>	<u>Maple</u>	<u>Maple</u>
Diameter	<u>7 1/2"</u>	<u>5"</u>	<u>5"</u>
Bearing	<u>N1E</u>	<u>S10E</u>	<u>S71W</u>
Distance	<u>40.07'</u>	<u>38.45'</u>	<u>5.15'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1986 Certificate - Ken Whitehorn
Doc # 289687

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____