

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration


Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R7

CASS COUNTY LAND CORNER RECORD



T. 143 R. 27 M. 514 Coordinates: X _____ Y _____
N1/4 29 Corner common to sections 20, 29

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees

Species	<u>Fir</u>	<u>Cedar</u>	_____	_____
Diameter	<u>10"</u>	<u>6"</u>	_____	_____
Bearing	<u>S57E</u>	<u>N55E</u>	_____	_____
Distance	<u>8 LKS</u>	<u>2 B LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search 4-99 By J. FOSTER
0.260m Red Pine S53°W
29.156m to spike in NW face up to 0.130m
4'x4' post N2°W 5.438 to 20d nail in E face up 0.170m
0.279m Power Pole N51°E
16.482 to 20d nail in SE face up 0.250m
Quarter corner Brass capped concrete
monument 0.24m
0.250m Red Pine S34°W
22.434m to spike in NW face up 0.370m

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

CERTIFICATE OF LOCATION 5/5/99
 DOC NO. 412418

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____