

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____

= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 35 Corner common to sections 25, 26, 35, 36



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument Post

Species	Bearing	Trees	
<u>Spruce</u>	<u>Fir</u>	<u>Fir</u>	<u>Fir</u>
Diameter <u>10"</u>	<u>6"</u>	<u>6"</u>	<u>5"</u>
Bearing <u>S55W</u>	<u>N6W</u>	<u>S34E</u>	<u>N38E</u>
Distance <u>50LKS</u>	<u>10LKS</u>	<u>9LKS</u>	<u>14LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1915 By JOHN CLRO
 Location filed COUNTY BOOK "B" P455-462
 Monument TWO OWNED 5x5 DEAD SPRUCE SAWARD 4 SIDES FOR CORNER. ALSO REMAINS OF OLD STAKE AND DOWN 6" FIR S34E 9 LKS, ROOTS OF OTHER BIRCH SET 3x3x48" POST

Bearing Trees, Reference Objects
 Species W. PINE STUMP W. PINE STUMP
 Diameter 40" 40"
 Bearing S24-30E S47W
 Distance 30.90' 56.00'

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

← also on microfilm - roll 115 BK 79 P 23-24

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search 1998 By L. LEWELLING (NLSM)
Set a 1 1/2" x 24" galv. steel pipe w/ a brass cap below the bit. Located 10.8' S of E CO. RD. 4 and 6.6' East of E RD running north, and 10.8' West of E RD running south.

REF. TIES:
14" Aspen N12°E 103.02' (31.400m)
5" Birch S28°E 123.98' (37.788m)
Steel signpost south 63.06' (19.220m)
to E Flange F.S. sign 54-9
11" Aspen S5°W 62.01' (18.902m)
9" Maple N52°W 101.25' (30.860m)

CERT. OF LOCATION 5-30-99
 DOC. NO. - 413418