


Index No. V 3

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
N1/4 31 Corner common to sections 30, 31



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument Post

Bearing Trees
 Species Cedar Birch
 Diameter 6" 6"
 Bearing S34E North
 Distance 4LKS 9LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1928 By GLO
 Location filed Sec. of State
 Monument Set 1x36" I.P. w/brass cap at proportionate distance
1/2 530
1/2 531
1928

Evidence of Subsequent Corner Restoration
 Year of search 1980 By Walter Curo
Found GLO monument in good condition.

Bearing Trees, Reference Objects
 Species NO B.T.S Set cedar post 4x4"x5' HIGH
 Diameter alongside iron post
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

<u>Birch</u>	<u>Elm</u>	<u>W. Oak</u>	<u>Aspen</u>
<u>10"</u>	<u>5"</u>	<u>8"</u>	<u>12"</u>
<u>N40W</u>	<u>N6W</u>	<u>N58E</u>	<u>S73E</u>
<u>31.58'</u>	<u>33.10'</u>	<u>41.98'</u>	<u>22.5'</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
1975 Certificate - William Okerman
Doc # 223550
1980 Certificate - Walter Curo
Doc # 291489

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____