

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_


Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

T. 143 R. 27 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	<u>Spruce</u>	<u>Willow</u>	<u>Spruce</u>	<u>Spruce</u>
Diameter	<u>8"</u>	<u>7"</u>	<u>10"</u>	<u>10"</u>
Bearing	<u>S54E</u>	<u>N45W</u>	<u>S71W</u>	<u>N47E</u>
Distance	<u>11LKS</u>	<u>16LKS</u>	<u>18LKS</u>	<u>17LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1912 By HARRY S. TODD  
Location filed COUNTY SURVEY RECORD BOOK "A" P 542-543  
Monument FIND 4x4x48" STAKE SET BY CURD TOWN OLBOUT  
BITS (NOW CUT DOWN)  
1915 JOHN CURD COUNTY BOOK "B" FIND 4" POST SET BY  
CARD.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
← 1915 - also on microfilm - roll 115 BK "A" P. 4

Bearing Trees, Reference Objects

Species	<u>CEDAR</u>	<u>CEDAR</u>	<u>TAM.</u>	<u>TAM STUMP</u>
Diameter	<u>4"</u>	<u>6"</u>	<u>10"</u>	<u>8"</u>
Bearing	<u>S49-52E</u>	<u>S44-08W</u>	<u>N39-16W</u>	<u>N61-58E</u>
Distance	<u>28.70'</u>	<u>23.61'</u>	<u>58.12'</u>	<u>34.97'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By L. EUELLING (NLSM)  
Set a 4 1/2" x 24" galv. steel pipe w/ brass  
cap in the E of Co. Rd. 4 down 10"  
below grade. Old cleared line to the  
So. of cor.

REF. TIES

<u>5" Ash</u>	<u>N 19° W</u>	<u>85.00' (25.909m)</u>
<u>7" Ash</u>	<u>N 38° E</u>	<u>96.42' (29.390m)</u>
<u>5" Ash</u>	<u>S 21° E</u>	<u>117.84' (35.918m)</u>
<u>13" Ash</u>	<u>S 22° W</u>	<u>114.52' (34.906m)</u>
<u>Steel Signpost</u>	<u>S 6° E</u>	<u>96.89' (29.533m)</u>

CERT. OF LOCATION S-30-99  
DOC. NO. 413445