


Index No. W-X 5

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
MC # 14 Corner common to sections 31, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	
Diameter	<u>7"</u>	<u>5"</u>	
Bearing	<u>SSE</u>	<u>S4W</u>	
Distance	<u>224 LKS</u>	<u>232 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

O = Corner

Subsequent Corner Restoration

Year surveyed 1928 By GLO
Location filed Sec. of State
Monument Set 1x36" i.p. w/ brass cap et proportionate distance - on left bank of river
ML
531/532
T143N R27W
1928

Bearing Trees, Reference Objects

Species	<u>No bits -</u>	<u>Set 8"x3"x6' Cedar post</u>
Diameter	<u>alongside iron.</u>	
Bearing		
Distance		

Evidence of Subsequent Corner Restoration

Year of search 1998 By J. FOSTER (NLSM)
find & remonumented the 1928 GLO survey meander corner. Aluminum capped, Alum. rod.
CERT. OF LOCATION - 6-2-99
DOC. NO. - 413582

Bearing Trees, Reference Objects

St. Signpost	<u>Signpost</u>	<u>Signpost</u>
EAST	<u>SOUTH</u>	<u>NORTH</u>
<u>2.07'</u>	<u>2.26'</u>	<u>1.92'</u>
<u>(0.632m)</u>	<u>(0.688m)</u>	<u>(0.586m)</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared _____ By _____
Filed at _____ Date _____