


Index No. X 13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E14 33 Corner common to sections 33, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Birch Birch \_\_\_\_\_  
Diameter 10" 10" \_\_\_\_\_  
Bearing S35E N22W \_\_\_\_\_  
Distance 5 LKS 9 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

○ = Corner

Subsequent Corner Restoration

Year surveyed 1969 By William OKerman  
Location filed \_\_\_\_\_  
Monument Set 24" concrete monument with brass cap.

Evidence of Subsequent Corner Restoration

Year of search 4-99 By J. FOSTER  
0.051m Iron Pipe N 89°W 4.834m up 0.430m  
0.310m Birch W 16.436m to spike in S face up 0.170m  
0.240m ELM STUMP W 12.646m to 2nd rail in E face up 0.010m  
Cedar Post E 3.798m to 2nd rail in N face up 0.130m  
0.200m Red Maple 583°E  
19.450m to 2nd rail in W face up 1.330m  
0.200m Basswood 52.5°W  
16.160m to spike in S face up 1.600m  
Certificate location 5/5/99  
DOC. NO. 412421

Bearing Trees, Reference Objects

Species Elm Elm Balsam Cedar Post  
Diameter 7" 5" 4" \_\_\_\_\_  
Bearing West S12W N58E East  
Distance 42.05' 76.64' 24.75' 12.40'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1975 Certificate - William OKerman  
Doc # 223552

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_