


Index No. X 2

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
C.W. 116 Corner common to sections 31



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1928 - GLO
Original monument 1X36" 1/2 P. W/brass cap C W 116 C
531
1928

Bearing Trees
Species Cedar Cedar
Diameter 6" 6"
Bearing N55E N72 1/2 W
Distance 46 LKS 59 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1970 By William OKerman
Location filed _____
Monument Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species Birch Cedar Aspen
Diameter 5" 11" 8"
Bearing N1E N38W S4W
Distance 43.90' 34.60' 59.60'

Evidence of Subsequent Corner Restoration

Year of search June 2002 By CCSO
Found 2" ODIP, tipped, 6' ± S. of
& county road #4.

Bearing Trees, Reference Objects

Ash Aspen Spruce
6" 8" 10"
N12°E S18°E S40°W
75.66 30.27 40.25

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1975 Certificate - William OKerman
Doc. # 222947

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____