


Index No. X3

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 57A Coordinates: X _____ Y _____
C14 Corner common to sections 31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1928 - GLO C14
Original monument 1x36" h.p.w/brass 531
cap 1928

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species NO B.TS - Set 4x4x6' High alongside iron
Diameter _____ post
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1970 By William Okerman
Location filed _____
Monument Found GLO monument in good
condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1975 Certificate - William Okerman
Doc. # 222946

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____