


Index No. X 9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
E 1/4 32 Corner common to sections 32, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Spruce</u>	<u>Spruce</u>	_____
Diameter	<u>7"</u>	<u>6"</u>	_____
Bearing	<u>N59W</u>	<u>N30E</u>	_____
Distance	<u>15cks</u>	<u>11cks</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1975 By William OKerman
Location filed _____
Monument Set 60" galvanized steel pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1975 Certificate - William OKerman
Doc. # 223546

1999 - J. FOSTER RLS # 25342
Fnd. impl. 1968 USDA-F.S. monument (2"x 5'
galv. steel pipe w/ 3" Brass cap)
REF: Steel signpost NORTH 5.65'
" " EAST 8.70'
" " SOUTH 8.23'

CERT. OF LOCATION 5/25/99
Doc. # 413185

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____