


T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____
E 1/4 3 Corner common to sections 2, 3



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Bearing	Distance
<u>Birch</u>	<u>N 28 W</u>	<u>8 LKS</u>
<u>Spruce</u>	<u>S 62 E</u>	<u>10 LKS</u>
_____	_____	_____
_____	_____	_____
_____	_____	_____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By HARRY S. TODD
 Location filed COUNTY SURVEY RECORD BOOK "A" P 532-535
 Monument END OLD GOVT B.T.S. STUMP 8" SPRUCE
S 62 E 10 LKS, STUB 8" BRWT N 28 W 8 LKS.
SET 2" X 48" GALV. I.P. W/CAP
also on micro film - roll 115 BK 74 P 60

Evidence of Subsequent Corner Restoration

Year of search 1959 By Co Hunt Dept
CORD # B - SP 11-615-01 BK 2
I.P.

Bearing Trees, Reference Objects

Species 1.62 - set 4x48 pipe for corner
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1916 By H.F. Baldwin
 Location filed micro film - roll 115 BK 77 P. 58, 59
 Monument End I.P. w/cap checks with stump
of SE Spruce B.T.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____